

GAS WELL INCIDENT REPORT FORM

Facility Information	Facility Name: <u>Overcoming Faith</u> Address: <u>4700 Eden Rd</u> City: <u>Arlington Texas</u> County: <u>Tarrant</u>
Responsible Party (RP) Information	Contact Person: <u>Brian Benge(Cornerstone N.G. Engineering, LP)</u> Phone: <u>817-348-0700</u> Company: <u>Edge Barnett Operating</u> Fax: _____ Address: <u>616 Texas St. #102</u> City: <u>Fort Worth</u> State: <u>Texas</u> Zip: <u>76102</u>
Release reported by (if different than RP):	Contact person: <u>911 Phone call</u> Phone: _____ Company: _____ Address: _____ City: _____ State: _____ Zip: _____

RELEASE DETAILS

<input checked="" type="checkbox"/> Confirmed <input type="checkbox"/> Suspected	Date discovered: <u>8/27/2013</u>	Date reported to TCEQ/RRC: <u>8/27/2013</u>	<input type="checkbox"/> Separator <input type="checkbox"/> Wellhead <input type="checkbox"/> Sales line	<input type="checkbox"/> Tanks <input type="checkbox"/> Compressor <input checked="" type="checkbox"/> Piping
---	-----------------------------------	---	--	---

Comments/Notes

On 8/27/2013 the Arlington Fire Department was dispatched to the Overcoming Faith Drill site as a result of a citizen complaint. According to the 911 dispatch the details of the complaint are as follows, "Gas Well Response, FD (Fire Department) is responding to 4700 Eden. Reference: hissing and loud popping noises coming from gas well site. Upon arrival, per the Fire Inspector Jay White, the Emergency Shut Down (ESD) devise was utilized. However, well 6H did not properly shut-in. The situation was brought under control with manual isolation of the wells. A site investigation is underway to identify the root cause of the incident.

Detailed Violation Description:

As a result of well 6H's failure to shut-in properly after the activation of the ESD located on the Overcoming Faith Drill site, a notice of violation has been issued. Offense: failure to maintain automated valve that closes the well in in the event of an abnormal change in operating pressure. This is a violation of Ordinance No. 11-068, Article VII, Section A, line 13.

Additional Information:

Incident reported to the Rail Road Commission Engineer, Marshall Berryhill at 9:20am on 8/27/2013.

Please contact Jessica Minley, Gas Well Specialist, for any follow up question regarding the above incident and/or violation issued.
